

# Screw Press Upgrade Products

## Double Helix at SCP Inlet Section

### The Situation:

#### **Screw Press Feed Problems, reduced production efficiency**


- Plugging of inlet screens due to low inlet consistency and high content of fines results in reduced filtration area and decreases the discharge consistency

# Screw Press Upgrade Products

## Double Helix at SCP Inlet Section

### The Solution:

install double helix in the inlet zone



#### Installation of a second helix in the inlet zone

- results in a cleaning effect of the baskets from the fines
- reduces the moisture pressure on the basket surface due to increased flight frequency